

## Service Bulletin

File in Section:

Bulletin No.: 16-NA-108

> Date: April, 2016

## **TECHNICAL**

Subject: Buzz or Static Noise from Radio Audio Speakers, Android Auto Connection Issues,

Intermittent Black Screen or Sirius XM Reverts to XM1 Channel Intermittently

Attention: This Bulletin also applies to any of the models that may be NA Export vehicles.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	]	
Chevrolet	Camaro	2016	2016		-	All	All
Chevrolet	Cruze	2016	2016			All	All
Chevrolet	Malibu	2016	2016			All	All
Chevrolet	Silverado	2016	2016			All	All
Chevrolet	Spark	2016	2016			All	All
GMC	Sierra	2016	2016			All	All

Condition	Some customers may comment on one or more of the following conditions: <ul> <li>a buzz or static noise from the radio audio speakers</li> <li>Android Auto connection issues (ex. does not launch automatically, black screen, etc.)</li> <li>Sirius XM reverts to XM1 channel intermittently.</li> </ul>	
Cause	This may be the result of a radio calibration concern.	
Additional Options	Equipped with Chevy MyLink or GMC IntelliLink Radio (RPO IOA or IOB)	

## Correction

If you encounter a vehicle with the above concern, USB and then SPS program the radio with the latest TIS2 Web calibrations, which are designed to address this concern and titled: New Software to Address Audio Buzzing and Static Issues.

Refer to Radio Programming and Setup in SI.

Note: If programming a Chevrolet Spark, you may have to select GM Korea within TIS2 Web to select the vehicle.

## **Warranty Information**

Labor Operation	Description	Labor Time
2810335	Radio Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	