



# Service Bulletin

## PRELIMINARY INFORMATION

**Subject:** Service Park Assist Message At Start Up With DTC U0159

**Models:** 2016 Cadillac Escalade Models  
2016 Chevrolet Silverado, Suburban, Tahoe  
2016 GMC Sierra and Yukon Models  
With Ultrasonic Park Assist System (RPO UD5 or UD7)

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some owners may comment at times when they first start their vehicle, a "Service Park Assist" message is displayed. If they cycle the ignition off and back on, the message will be gone. When scanning for DTC's, a U0159 will be set in the IPC and/or BCM.

**Note:** This concern only occurs at start up and is very random. This PI does not apply to any other Park Assist DTC's, or if the issue occurs some time after start up.

### Recommendation/Instructions

Engineering is currently working on an updated calibration to correct this concern. At this time, advise the customer to cycle the ignition off and then back on to clear the issue.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION