



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-191

Date: June, 2016

TECHNICAL

Subject: Side Detection System Message Being Displayed on Driver Information Center (DIC), DTC B101E Set

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox, Impala (VIN 1)	2016	2016				
GMC	Terrain	2016	2016				

Involved Region or Country	North America
Additional Options (RPO)	Some customers may comment on the service side detection system message being displayed on the driver information center (DIC). Technicians may notice DTC B101E code set or stored in history.
Cause	This condition may be caused by a software anomaly.

Correction

Update the side object sensor with the latest software.

Note: Left and right sensors need to be sequenced together for programming.

Service Procedure

Refer to *Side Object Sensor Programming and Setup* in SI.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810765	Side Object Sensor Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION