



Service Bulletin

PRELIMINARY INFORMATION

Subject: Water Rush Or Gurgle Noise From Heater Core

Models: 2015 - 2016 Chevrolet Colorado
2015 - 2016 GMC Canyon

This PI was superseded to update the Models section. Please discard PIT5420A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The customer may note a water rush or gurgle type noise from the center dash area.

The technician may isolate this noise to the heater core caused by air in the cooling system.

Recommendation/Instructions

Engineering is aware of the concern and it is under investigation.

Inspect the system for coolant leaks and proper coolant level.

No other repairs are to be performed at this time.

PI will be updated or bulletin will be released when more information is available.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION