



TECH TIP: DTC P200A returns after VCMA replacement and reflash procedure

NUMBER: TT035

MODEL: 2011-13 Sorento (XM)

DATE: 01/13/2014

Symptom: Returning code P200A on a Sorento with a V6 and have already replaced the VCMA and the lower intake as well as performed the VCMA relearn procedure with the GDS. What should be checked next?

Repair: Test the vehicle battery with the GR8. If the battery fails the test then it should be replaced and the VCMA relearn procedure should be performed with the GDS.

Note: Tech Tips are not a substitute for proper diagnosis.