Part 573 Safety Recall Report 20V-053

Manufacturer Name : Jaguar Land Rover North America, LLC
Submission Date : MAR 04, 2020
NHTSA Recall No. : 20V-053
Manufacturer Recall No. : N422

Manufacturer Information :

Manufacturer Name : Jaguar Land Rover North America, LLC
Address : 100 Jaguar Land Rover Way
Mahwah NJ 07495
Company phone : 8188500

Population :

Number of potentially involved : 34
Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2020 Land Rover Discovery
Vehicle Type : LIGHT VEHICLES
Body Style : SUV
Power Train : GAS
Descriptive Information : Jaguar Land Rover are conducting a voluntary safety recall campaign involving certain Land Rover Discovery 2020 Model Year vehicles built at the Nitra vehicle assembly plant in Slovakia from September 11, 2019 to November 19, 2019.

17 Land Rover Discovery 2020 Model Year vehicles in the United States and Federalized Territories.

17 Additional Land Rover Discovery 2020 Model Year vehicles in the United States and Federalized Territories.

Total = 34 vehicles in the United States

The basis of the recall population was derived from supplier data where the defect could be traced to individual vehicle VINs from SALRR2RV9L2419697, built September 11, 2019 to SALRR2RK8L2429367 built November 19, 2019.

Production Dates : SEP 11, 2019 - NOV 11, 2019
VIN Range 1 : Begin : SALRR2RV9L2419697 End : SALRU2RV8L2429524 ☐ Not sequential

Description of Defect :

Description of the Defect : A concern has been identified on certain 2020 Model Year Land Rover Discovery vehicles where some of the fasteners of the second row seat frame assembly may be missing. Where one or more seat fasteners are missing, the seat will not have sufficient structural integrity.

FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	In the event of a crash, there is an increased risk of injury to the occupants of the vehicle.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	NR

Supplier Identification :

Component Manufacturer

Name :	Brose CZ spol. s r.o
Address :	Průmyslový Park 302, 742 21 Kopřivnice FOREIGN STATES
Country :	Slovakia

Chronology :

See file "Recall N422 Chronology".

Description of Remedy :

Description of Remedy Program :	Land Rover will notify owners, and authorized repairers will replace the second row seat frame and ensure the bolts are to the correct torque. The affected vehicles will be covered under Land Rover's new vehicle warranty program. There will be no charge to owners for this repair.
How Remedy Component Differs from Recalled Component :	Second row seat frame - Left - With power seat recliner – LR081084 Second row seat frame - Left - Without power seat recliner – LR081082 Second row seat frame - Right - With power seat recliner - LR081081 Second row seat frame - Right - Without power seat recliner - LR081080
Identify How/When Recall Condition was Corrected in Production :	NR

Recall Schedule :

Description of Recall Schedule :	Distribution of owner notification letters will occur on or before March 19, 2020. Notifications to dealers will occur on February 13, 2020.

Planned Dealer Notification Date :	FEB 13, 2020 - FEB 13, 2020
Planned Owner Notification Date :	MAR 19, 2020 - MAR 19, 2020

* NR - Not Reported