From:
To:
Subject:
Date:

Trouble viewing this email?

Date: August 13, 2021
Attn: Slingshot Dealer Personnel
Subject: Safety Recall T-21-01 Released
Questions: Contact Polaris Technical Service

Dear Slingshot Dealer,

Please review the following communication that was posted on Friday, 08/13/2021.

Polaris has determined that some 2020-2021 Slingshot vehicles may have rear wheel studs that were not pressed into the axle fully during the supplier's assembly process. An improperly installed rear wheel stud could lead to loosening of the rear lug nuts, resulting in a loose or detached rear wheel during operation, increasing the risk of a crash.

This recall has been released to instruct dealers to complete the outlined inspection to identify any improper axle assemblies and replace if necessary.

- Click **HERE** to view T-21-01
- Click **HERE** to view FAQ

Thank you for your attention.

Sincerely,
Polaris Service

This email was sent by Polaris Inc. to

Privacy Policy

© 2021 Polaris Inc.
2100 Highway 55, Medina, MN 55340, USA | Polaris.com