



GM Over-The-Air (OTA) Software Update

Update Title	GM Update 663.30
Associated Field Action(s)	N25-253549 N25 252206 N25 252362 N25-252723 N25-253883 N25-253409 N25-253330 N25-253978 N25-253880 N25-252256 N25-253600 N25-253916 N26-255417 N26-255745 N25-251670 N26-256259 N26-255745 N26-255450 N26-255746 N26-256577
Release Notes	• After this update, you may need to turn your Turn Signal Activated View setting back on • Fixes to help ensure start reliability and prevent battery drain • Updates to enable memory seat buttons to be linked to a user profile. Up to two user profiles can be linked to your vehicle's memory seat buttons. • Improved charging performance and messages • Better performance and reliability of wireless phone charging
Model Year	2026
Make	GMC
Model	<u>Hummer EV</u>

Components	CGM-GTW (Communication Gateway Module) EBCM (Electronic Brake Control Module) AMP (Amplifier) ACP3_MCU (ADAS Compute Platform 3 - Microprocessor Control Unit) ACP3_SOC (ADAS Compute Platform 3 - System On A Chip) RDCM (Rear Driver Control Module) BCM (Body Control Module) TPIM (Traction Power Inverter Module) LRR (Long Range Radar) VCU (Virtual Cockpit Unit) PTM (Power Tailgate Module) SRR (Short Range Radar) VICM (Vehicle Integration Control Module) WCM (Wireless Charger Module) VLM (Vehicle Leveling Module)
-------------------	--