



GM Over-The-Air (OTA) Software Update

Update Title	GM Update 7.90
Associated Field Action(s)	
Release Notes	Great News! Your vehicle keeps getting better. This update contains a required software change to help improve the overall software update and diagnostics process. During the update process, your radio may stay on up to 5 minutes after you exit the vehicle. This is expected behavior when an update package is onboard the vehicle. Do not service your vehicle during installation.
Model Year	2027
Make	GMC Chevrolet
Model	<u>Equinox</u> <u>Terrain</u>
Components	CGM-OTA (Communication Gateway Module - OTA Micro) CGM-GTW (Communication Gateway Module) EBCM (Electronic Brake Control Module) BCM (Body Control Module) SRR (Short Range Radar) LRR (Long Range Radar) ACP2 (ADAS Compute Platform 2) AOS (Automatic Occupant Sensing Module) ECM (Engine Control Module) ELM (Exterior Lighting Module) EPS (Electronic Power Steering) TCP (Telematics Connectivity Platform) MSM (Memory Seat Module) PTM (Power Tailgate Module) SBZA (Side Blind Zone Alert) SDM (Sensing & Diagnostic Module) TCM (Transmission Control Module) UPA (Ultrasonic Park Assist) VCU (Virtual Cockpit Unit) WCM (Wireless Charger Module)