Part 573 Safety Recall Report 19V-783

Manufacturer Name : Gulf Stream Coach, Inc.
Submission Date : NOV 08, 2019
NHTSA Recall No. : 19V-783
Manufacturer Recall No. : 102919

Manufacturer Information :

Manufacturer Name : Gulf Stream Coach, Inc.
Address : P. O. Box 1005
503 S. Oakland Avenue Nappanee IN 46550
Company phone : 999-999-9999

Population :

Number of potentially involved : 205
Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2020-2020 Gulf Stream Coach, Inc. Amerilite, Conquest, Innsbruck, Grand River, Kingsport, Trail Master- 218MB, 248BH, 247ABH, 238RK, 241RB, 199DD, 199RK, 198BH, 197BH, 189DD, 188RB, 19RD 19DS, 16RE
Vehicle Type : TRAILERS
Body Style :
Power Train : NR
Descriptive Information : Change in quality control personnel with units identified and inspected prior to that change being in compliance with the code standard. Recalled products failed to have the refrigerator cabinet properly sealed and is visually evident in the units that are identified as subject to this recall.
Production Dates : JUL 08, 2019 - OCT 25, 2019
VIN Range 1 : Begin : 1NL1G2228L1137660 End : 1NL1G2112L1138750 ☐ Not sequential

Description of Defect :

Description of the Defect : On certain model Amerlite, Conquest, Innsbruck, Grand River, Kingsport and Trail Master Travel Trailers manufactured by Gulf Stream Coach, Inc. (“GulfStream”) the gas Refrigerator compartment may not have been completely sealed according to NFPA 1192 5.4.5.1 specifications.
FMVSS 1 : NR
FMVSS 2 : NR
Description of the Safety Risk : An Increased risk of carbon monoxide or flammable unburned Liquid Petroleum (LP) gases may migrate into the living quarters of the travel trailer if the refrigerator compartment is not properly sealed. Failure to provide adequate seals to the refrigerator compartment thus isolating the refrigerator compartment from the living area of the travel trailer may increase the risk of fire, or carbon monoxide poisoning causing injury or death to occupants and/or damage to property.

Description of the Cause :	NR
Identification of Any Warning that can Occur :	NONE

Supplier Identification :

Component Manufacturer

Name :	NR
Address :	NR
	NR
Country :	NR

Chronology :

A recent RVIA inspection review for the affected production facility manufacturing the subject units, resulted in identifying this noncompliance. Gulfstream Coach, Inc. has decided to initiate this recall out of an abundance of caution and concern for the safety and well-being of our customers.

Description of Remedy :

Description of Remedy Program :	All identified travel trailers subject to this Recall will be required to be inspected and verified for proper seals and to be in compliance to the NFPA 1192 requirement as identified above. Work instructions will be provided to the selling dealer or repair facility of the owner's preference for completing this Recall to the travel trailers which have been identified as the subject of this Recall.
How Remedy Component Differs from Recalled Component :	NR
Identify How/When Recall Condition was Corrected in Production :	All travel trailers subject of this Recall and within the immediate control of "GulfStream" have been repaired prior to releasing for shipment to the selling dealerships.

Recall Schedule :

Description of Recall Schedule :	Gulf Stream Coach, Inc. has the utmost urgency in our recalls. The defect notification, to be sent to the vehicles listed dealer and/or the current owner as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.
Planned Dealer Notification Date :	NOV 18, 2019 - NOV 22, 2019

Planned Owner Notification Date : NOV 18, 2019 - NOV 22, 2019

* NR - Not Reported