CAMPAIGN LAUNCH STATUS

N499 RECALL - 10 & 11MY RANGE ROVER SPORT REAR SPOILER

SAFETY RECALL N499 REAR SPOILER UPPER COVER RETENTION	
AFFECTED MODELS	2010-2011 MY L320 Range Rover Sport
VOLUME AFFECTED	21,834 USA 1922 CAN
REPAIR	The rear spoiler cover may detach from the rear of the vehicle due to adhesive bond failure. New adhesive will be applied to the top cover. Damaged or missing spoiler covers are to be replaced. Reimbursement for prior repairs may be claimed after the recall repair claim is processed.
REPAIR TIME	0.5hrs for repair or 0.3hrs to replace spoiler + DIDO
CAMPAIGN LAUNCHED	May 7th, 2021 Updated July 8th, 2021
Notes	**Following Retailer feedback and an internal review, the reimbursement for painting a new rear spoiler has been increased to c $480.**