[redacted]

November, 2022

* * * IMPORTANT SAFETY RECALL REMINDER * * *

According to our records, your 2022 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **22C15 - Tire Pressure Monitoring TPMS Configuration**

What is the issue? On your vehicle, the tire pressure monitoring system (TPMS) light in your vehicle's instrument cluster may not illuminate when intended and may not be able to provide adequate warning of low tire inflation pressure.

Low tire pressure may lead to poor vehicle handling and a possible loss of vehicle control, increasing the risk of a crash.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.
If you wish to contact us through the Internet, our address is: ford.com/support.

Thank you for your attention to this very important matter.

[redacted]

Noviembre de, 2022

* * * RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD * * *

SegUR nuestros registros, no se realizaron en sur 2022 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **22C15 - Configuración del sistema de monitoreo de presión de las llantas TPMS**

¿Cuál es el problema? La luz del sistema de monitoreo de presión de las llantas (TPMS) en el tablero de instrumentos de su vehículo podría no encenderse cuando corresponde y podría no proporcionar las alertas adecuadas de presión de inflado baja de las llantas.

Una baja presión de las llantas podría provocar una maniobrabilidad deficiente del vehículo y una posible pérdida de control, lo cual aumenta el riesgo de choque.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.
Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: ford.com/support.

Gracias por su atenciic en este asunto sumamente importante.

© Copyright 2022 Ford Motor Company

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID

R K C

0045144 A / 000000000000174 / 174

[redacted]

SEE OTHER SIDE FOR OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION

SEE OTHER SIDE FOR OPENING INSTRUCTIONS

REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION