SSM 48081 - 2019 Transit Connect - Perimeter Anti-Theft Security Alarm - Reduced Guard Control Function Disabled

Some 2019 Transit Connect vehicle owners may request a way to disable the enhanced security system to prevent motion from activating the vehicles anti-theft alarm. On exiting the vehicle, a menu will be displayed on the instrument panel cluster (IPC) that will allow a change in the alarm status to perimeter only. If the menu is not being displayed, use the latest version of the appropriate Ford diagnostic scan tool and run the IPC – Anti-Theft Configuration application. Thiswill enable the menu on vehicle exit in the IPC.

APPLICABLE VEHICLES
 2019 CAR: TRANSIT CONNECT