SSM 48930 - 2020 Navigator, 2020 Corsair - Various DTCs Stored In The Remote Function Actuator (RFA) Module

Some 2020 Navigator and 2020 Corsair vehicles may have diagnostic trouble codes(DTCs) P1269, B1A56, B1D55, B1589, and/or B1590 through B1598 stored in the RFA module with no reported customer symptoms. If these DTCs are detected during pre-delivery inspection (PDI) or while diagnosing unrelated conditions, they should be disregarded.

APPLICABLE VEHICLES
 2020 TRUCK: B9 U554N NAVIGATOR
 2020 CAR: TF CX483N CORSAIR