




PART NUMBER:	ISSUE	4/8/2021	SUBARU OF AMERICA	PAGE 1/3
C1010CC100	01	4/8/2021	SUBARU OF AIVIERICA	PAGE 1/3




## PART NUMBER: C1010CC100





STEP 3: Remove the factory shift knob.




PART NUMBER:	ISSUE	4/8/2021	SUBARU OF AMERICA	PAGE 2 / 3
C1010CC100	01	4/8/2021	SUDANU OF AIVIENICA	PAGE 2 / 3




## PART NUMBER: C1010CC100


STEP 4: Gently position STI Leather Shift Knob on shift lever. Ensure knob is straight and level. **Note:** Do not tighten if the knob is crooked, doing so may damage the threads or cause them to crossthread.



STEP 5: Turn STI Leather Shift Knob clockwise until tight. Do not overtighten. If needed, turn the knob slightly counter-clockwise until the STI logo is in the correct orientation.



STEP 6: Check the operation of the shift lever by moving it through each gear including reverse. Installation Complete.



PART NUMBER:	ISSUE	4/8/2021	SUBARU OF AMERICA	PAGE 3 / 3
C1010CC100	01	4/8/2021	SUDANU OF AIVIENICA	PAGE 3 / 3