General Service Bulletin (GSB):	Instrument Panel Cluster Mask / Lens Warranty				
GSB Overview:	Information on warrantable vs non-warrantable conditions along with proper cleaning procedures and how to order replacement displays				
NOTE: This information is not intended to replace or supersede any warranty, parts and service policy, Work Shop Manual (WSM) procedures or technical training or wiring diagram information.					

This GSB includes information on the following topics:

- Proper cleaning procedures of the Instrument Panel Cluster Lens
- Warrantable and non-warrantable conditions
- How to order a replacement Instrument Panel Cluster / Mask / Lens

Cleaning the Mask / Lens

Cleaning:

Refer to the Owner Manual for vehicle specific cleaning procedures. Damage to the Mask / Lens can be induced if the proper cleaning procedure is not being followed, such as using spray-type glass cleaning products.

- Use a clean, soft cloth such as one used for cleaning glasses.
- Do not pour or spray alcohol onto the Mask / Lens.
- Do not use detergent or any type of solvent to clean the Mask / Lens.

Repairs That Are Not Warrantable

Per warranty policy, screens with indications of non-warrantable damage such as:

- Accidents or objects striking the screen
- Theft, vandalism, fire or explosion
- Using contaminated or improper cleaning fluids
- Customer-applied chemicals or accidental spills
- Cracks/Distortion due to devices or objects being attached to the display
- Damage caused by Alterations/Modifications

Refer to the Ford Warranty & Policy Manual for any questions.

See attached pictures for reference:

EXAMPLES OF MASK / LENS ISSUES THAT ARE NON-WARRANTABLE



Figure 1

Figure 2

Damage due to improper cleaning solutions or liquid spills (Figures 1 & 2)

Instrument Panel Cluster Coverage Version 1.0

Ford Motor Company Printed Copies Uncontrolled

September 2016 Page 3 of 8

EXAMPLES OF MASK / LENS ISSUES THAT ARE NON-WARRANTABLE



Figure 3

Figure 4

Damage due to improper cleaning

(Figures 3 & 4)

Instrument Panel Cluster Coverage Version 1.0

Ford Motor Company Printed Copies Uncontrolled

September 2016 Page 4 of 8

EXAMPLES OF MASK / LENS ISSUES THAT ARE NON-WARRANTABLE



Figure 5

Figure 6

Damage due to excessive force or impact to the Mask / Lens

(Figures 5 & 6)

Instrument Panel Cluster Coverage Version 1.0

Ford Motor Company Printed Copies Uncontrolled

September 2016 Page 5 of 8

EXAMPLES OF MASK / LENS ISSUES THAT ARE NON-WARRANTABLE



Figure 7

Figure 8

Damage due to scratches on the Outside Surfaces

(Figures 7 & 8)

Instrument Panel Cluster Coverage Version 1.0

Ford Motor Company Printed Copies Uncontrolled

September 2016 Page 6 of 8

EXAMPLES OF MASK / LENS ISSUES THAT ARE WARRANTABLE



Figure 9

Figure 10

Cracked Mask / Lens and Scratches on the Inside Surface (Provided no non-warrantable damage, modifications or tampering is evident)

(Figures 9 & 10)

Instrument Panel Cluster Coverage Version 1.0

Ford Motor Company Printed Copies Uncontrolled

September 2016 Page 7 of 8

Ordering Process Using Ford Catalog Advantage

- Log into PTS using a VIN
- Click on "Parts Catalog" under the Workshop tab and enter the Lens/Mask base part number of "10890" in the "Search" field and hit "Go"
- The correct lens/mask part number will be displayed in the "Search Results" field

DMS Home Find Price Bookmark Links Settings Support About									
Textual Search Illustrated Index Shopping TUB Explorer 2016,									
SET VEHICLE	8	Search TUB Explorer							
by VIN		Base O Description	⊖ SPN ⊖ Motorcraft	O Associated Part No.			_		
VIN	1FM5K8HT7GGC	Search: 10890 Go						T	
Last 10 VINs	~							-	
Favorite VINs	~	Cross Reference Search						-8	
Add to Favorite VINs	Edit Favorite VINs	EPN:		60					
		VIN Results Search Res	sults						
by Model Category	Light Trucks	Results 1-1 out of 1	Result Pages: [1]						
Model Year	2016	Callout No.		Description		Section			
Model	TUB Explorer	10890	8	Mask		05D Instrument Cluster, 2016/ Fr Instrumentation	om: 07/06/201	L5 ; High	
Configuration Setti									
Vehicle Line	Explorer								
Positive Territories	(+)"USA"								
Engine Type	3.5L DOHC T/C V6 Gas 💌								
Transmission	6 Speed Auto Transmis								
Air Conditioning	Dual Zone Auto Temp (
Cab Style	Regular Wagon	Transmit to DMS	dd to Shopping List New L	ist 🗸 🗸 Price Dealer Cost 🗸	🔹 d2dlink 🕀 <u>Show All Columns</u>				
Drive	LHD 4WD (FTD)	Results 1 - 1 out of 1	Result Pages: [1]						
Series	Ford Series	SPN SPN	Motorcraft	Application Info			Model Year	Price	
Final Drive Ratios	3.16 Ratio	GB5Z-10890-E	I	From: 07/06/2015 2016/			2016/	11.90	
Exterior Paint	White Platinum								
Interior Environment	Ebony Black/Ebony Blac								
Interior Fabric	Leather C / Ebony Black								
	Apply Reset								

Ford Motor Company Printed Copies Uncontrolled

September 2016 Page 8 of 8