


Police Interceptor Utility One Piece Catalytic Converter Manifold

General Service Bulletin (GSB):	One Piece Catalytic Converter Manifold
GSB Overview:	This Bulletin Provides Additional Information For Making The Correct Warranty Decision When Encountering Cracked One Piece Catalytic Converter Manifolds on 2013 – 2017 Police Interceptor Utility Vehicles With 3.7L Ti-VCT Engine
NOTE: This information is not intended to replace or supersede any warranty, parts and service policy, Work Shop Manual (WSM) procedures or technical training or wiring diagram information.	

If a 2013 – 2017 Police Interceptor Utility vehicle is found with a cracked one piece catalytic converter manifold, warranty should not be denied or cancelled due to impact damage found on the exhaust Y-pipe assembly. Existing warranty coverage should be honored on the one piece catalytic converter manifold if such a condition is found. This does not extend to any damage found on the Y-pipe and if found the Y-Pipe is not warrantable. Refer to the below images and illustrations.



Examples of impact dents to y-pipe assembly

