2025-06-13



M1696: 2025 CVO ROAD GLIDE RR (FLTRXRRSE) CLUTCH INSPECTION COVER CHANGE

Reason for Revision

Refer to Table 1.

Table 1. Document History

	Rev	(
2025-06-13	-	Initial release

Purpose for Service Bulletin

M1696

This bulletin informs dealers that the Clutch Inspection Cover on 2025 CVO Road Glide RR (FLTRXRRSE) models has been changed from the original released version with painted accents (Part No. 25702011) to one without painted accents (Part No. 25702011A) as part of a running change. Early motorcycles were built with covers with the painted accents and later models will arrive without the painted accents.



Figure 1. Painted Accents Part No. 25702011



Figure 2. Unpainted Accents Part No. 25702011A

Required Dealer Action

Table 2. Required Dealer Action

	Category	Description	Required		
1 Musi		Must Perform Repair			
2 Repa		Repair If Presenting Symptom			

Table 2. Required Dealer Action

Category	ategory Description	
3	Feature Pack- Customer/Dealer Paid	
4	Informational Purposes Only	

If a motorcycle has a cover with painted accents and the paint begins to peel from the cover, dealers should replace the cover with the updated cover without painted accents and file the appropriate warranty claim if the vehicle is within the warranty period.

The replacement Clutch Inspection Cover (Part No. 25702011A) will arrive without painted accents and should be installed as is.

Dealers do not need to retain the painted clutch inspection covers (Part No. 25702011) per the standard Warranty Parts retention policy and parts can be provided to the customer to keep once the new unpainted part is installed.




Figure 3. Clutch Inspection Cover

Vehicles Affected

2025: CVO Road Glide RR (FLTRXRRSE)

Markets Affected

United States only.

Part Numbers

Refer to Table 3.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service

in the interest of preserving destrine sealed and sealed in the interest any meteroyale to brought into your dediction processing to earlier maintenance of service.									
ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									

Table 3. Part Numbers

Old Part No.	Item Description	New Part No.
25702011	Cover, clutch inspection	25702011A

2 / 2 M1696