



GROUP

General

MODEL

2026MY
Sportage (NQ5a)

NUMBER

PS811

DATE

May 2026






TECHNICAL OPERATIONS

SUBJECT:

ENGINE BAY/DASHBOARD RATTLE NOISE

This Pitstop provides information related to an intermittent rattle or tapping noise heard from the engine bay or dashboard area while driving on 2026MY Sportage (NQ5a) vehicles. The fuel feed and vapor tube bracket (A) may rattle/tap against the brake booster (B) while driving. Inspect the bracket for the proper positioning of the bracket, and reposition it as needed.



NOTICE

A Pitstop provides information which may help guide technicians address a concern on the subject vehicle described in this publication. A Pitstop is an informational guide/tool without customer notification. Technicians are to review the information provided in this Pitstop for the applicable vehicle and if applicable, use it for diagnostic purposes only. Dealers are required to validate Warranty Coverage in KDealer+ Warranty Coverage Inquiry before conducting any diagnosis/repair procedure.