

Possible Quality Issue Liner Kit DDE A4720111910

Communication Type: PDC

Date: 5/19/2026

Dear Valued Dealers,

Please review all inventory of **Liner Kit DDE A4720111910** with **date code K27K**.

It has been identified that these kits may contain an **incorrect liner (Part No. A4710112410)** instead of the correct liner **A4720112410**.

Required Action:

- Carefully inspect all inventory with **date code K27K**.
- Verify the liner part number inside each kit. **Incorrect liner (A4710112410)**.
- When an incorrect liner is identified, submit a **ZFRM PAR** and return the entire liner kit to your **Facing PDC**.

Please note that the **correct part number (A4720112410)** and the incorrect part number are similar. Extra care is required during verification to ensure accuracy.

If you have any questions or need assistance, please contact your Facing PDC.

Thank you for your prompt attention to this matter.

AMS Distribution Operations