

Bulletin #: C32-0526-0632		☐ Take Note ☒ Take Action	
☐ Retail Operator ☐ General Manager	☐ Sales Pre-Owned ☐ Sales New Car	☐ Business Manager ☐ Service	☒ Parts & Accessories ☐ Administration
Name:		Phone Number:	
Title:		Source: Parts Logistics	
Date: May 12, 2026		Supersedes:	



The **Ultimate**
Driving Machine®

BMW PARTS BULLETIN

TEC860 HOOD RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

41 00 7 381 758

Affected available inventory must not be used or sold.

Concerned are all parts delivered and shipped so far containing press defect on the inner edge of the front flap.

Your attention and information update is required on SRD Next>Parts Campaign by 05/15/2026.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC860 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC860 is valid from May 12, 2026, through May 26, 2026. The deadline for filing a claim under TEC860 is May 26, 2026. All parts must be returned to your facing RDC no later than June 09, 2026.

Please reorder the same part number as needed.

