

		MODEL I and Ix DINETTE DRAWER FRONT REPAIR INSTRUCTIONS			4 3 2 1 0 1 Difficulty Level
WI:	WI-089-2026 Model I and Ix Dinette Drawer Front Repair Instructions				
PRODUCT:	Model I and Ix	VIN Range:	000001 - 003366	REVISION:	REV-A
DATE:	May 18, 2026	LABOR RATE:	Labor Time: 0.3 Hours		

Instruction Overview

Certain Model I and Ix travel trailers equipped with the pull-out dinette table may experience a loose drawer front on the silverware drawer. The following instructions provide information on correcting this condition.

Safety:

Safety is and should always be observed when performing any type of repair or installation. ANSI (American National Standards Institute) has created a standardized labeling system for different levels of safety and danger. The labels below provides information regarding those levels of danger, and should be observed and adhered to at all times.

⚠ CAUTION

The “CAUTION” symbol above is a sign that a procedure has a safety risk involved and may cause personal injury, product and/or property damage if not performed safely and within the parameters set forth in this document.

⚠ CAUTION

CAUTION: Always wear Personal Protection Equipment (PPE), such as eye protection, ear protection, gloves and possibly a full face shield depending on the nature of the task to be performed.

TOOLS REQUIRED (NOT PROVIDED):

1. Screw gun
2. #2 Square drive bit



PARTS INFORMATION

PARTS LIST

PART #	Description	Qty
114379	FASTENER SCREW #8 X 1 1/4 5300 NATURAL CHOICE ROUND WASHER QUAD 2/3 DEEP THREAD PAINT-ED TYPE 17 W/(7M/BX)	4

WARRANTY INFORMATION

NO ADVANCED CONTACT OR PRIOR AUTHORIZATION REQUIRED

CLAIM REIMBURSEMENT PROCESSING:

All reimbursement requests with completed work orders, including any freight expenses and photographs, should be submitted via a claim in the Brinkley RV Dealer Portal. If you do not have access to our Portal, a claim can be emailed to VCB-Claims@Brinkleyrv.com.

REQUIRED INFORMATION FOR IMMEDIATE REIMBURSEMENT PROCESSING INCLUDES:

1. The full 17 digit VIN;
2. The Retail Name if retail sold;
3. Dealer Name;
4. Dealer Address;
5. Dealer Phone Number;
6. Dealer Hourly Labor Rate;
7. Work Order detailing the work performed and labor time, and
8. Before and after photographs of the completed repair.

Reimbursement checks for claims submitted with all requested information are issued weekly.



Work Instructions: WI-089-2026 Model I and Ix Dinette Drawer Front Repair Instructions



Revision Level: REV-A

Product: Model I and Ix

Page 2 of 3

WORK INSTRUCTIONS:

1. READ AND UNDERSTAND ALL INSTRUCTIONS PRIOR TO BEGINNING WORK.
2. Inspect the pull-out dinette silverware drawer to see if the drawer front is loose against the drawer frame (Figure 1). If it is, be sure the drawer front is centered on the drawer frame before proceeding to step #3.
3. Use a screw gun with a #2 square drive bit to install two (2) additional #8 X 1-1/4" wood screws (P/N 114379) through the drawer frame into the drawer front (Figure 2b and 2c). Position the screws offset as shown - one approximately 1" above the center line, and one approximately 1" below the center line.
4. Remove the original screws and replace them with new #8 X 1-1/4" wood screws (Figure 2c).



5. Repair complete.

