

TECHNICAL BULLETIN 264 – NEW MOTORCYCLE CONNECTION AND DIAGNOSTICS WORKFLOW

Triumph Motorcycles has released Technical Bulletin 264 covering a new workflow will automatically run a Smart Scan check on all motorcycle connections.

Attached is the full bulletin for your review.

 Technical Bulletin 264.pdf

- Please ensure your workshops and relevant staff are aware of the contents.
- Please also update your workshop service manuals, procedures, and have a printed copy available where appropriate.
- **PLEASE ENSURE ABSENT STAFF ARE INFORMED ON THEIR RETURN.
(Remember to update those returning from holidays/absence)**

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.