

Authored Date	14/05/2026	
Doc No.	IAMW0004502	
Title	Wheel Wrench Replacement	
Affected Vehicle(s)	Grenadier	PF000072 – PF009904 RF010491 – RF019001
Prior to starting any reworks, please make sure you check the vehicle is affected by checking the VIN using Vehicle Simple Search in the Warranty System.		

Reason for this document

Issue: An issue has been identified on a small percentage of the affected vehicles where the Wheel Wrench is defective.

Cause: The Wheel Wrench has not been manufactured to the correct specifications

Action: Follow the procedure below.

Workshop Procedure

Wheel Wrench – Remove and Install

Operation:	Repair Time:
Replace	0.1

Parts

Part Number	Description	Qty
GRA-0E99-058740	Wheel Wrench	1

Note:

- The procedure contains illustrations showing certain components removed to provide extra clarity.
- This procedure contains some variation in the illustrations depending on the vehicle specification, but the essential information is always correct.



Removal

1.

Open the front right door.

Refer to: TOPIC_0000002025 Door Front Right (Open and Close).

2.



- Remove the tool kit.
- Remove the wheel wrench.

Installation

1.

- Install the new wheel wrench.

Parts: GRA-0E99-058740 - Wheel Wrench. Quantity: 1

- Install the tool kit into its correct location.

2.

Close the front right door.

Refer to: TOPIC 000002025 Door Front Right (Open and Close).

3.

Release the vehicle.

Change History

Reference No.	Date	Description
IAMWO004502	24/05/2026	First release

