



# Service Bulletin

Bulletin No.: PIT6054D

Date: June, 2026

## PRELIMINARY INFORMATION

**Subject: Multifunction Inner Tailgate Disabling Procedure Inoperative**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2022 - 2026		All	All	All	All
Chevrolet	Silverado 2500/3500	2022 - 2026		All	All	All	All
GMC	Sierra 1500	2022 - 2026		All	All	All	All
GMC	Sierra 2500/3500	2022 - 2026		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPO)</b>	With QK2 - Multifunction Tailgate and without AVJ or ATH - passive entry
<b>Condition</b>	Multifunction Inner Tailgate Disabling Procedure Inoperative
<b>Cause</b>	If the vehicle is not equipped with RPO AVJ or ATH passive entry, it will not have the rear bumper antenna to allow the disabling of the inner tailgate.

### Correction

None, On vehicle without passive entry the inner tailgate cannot be disabled.

<b>Version</b>	5
<b>Modified</b>	08/28/2023 - Created on. 09/14/2023- Update model years. 02/19/2024- Update to additional options and cause sections. 12/11/2024 - Update model years. 06/05/2026 - Update model years.

