

9100831

06/04/2026

MY 20-26, 21-26, 18-26 DD 20-24, 21-24,
19-24 DF 20-24, 21-24, 21-23 DX 20-26,
19-26, 21-26, 18-26, 21-24 DJ 20-26, 21-
26, 18-26 DP 19-26, 21-26, 18-26, 21-23
D2 21-24 DS

GPOP - Issue Review System

Part Number: 68156426A\$, 68156427A\$, 68156428A\$, 68156429A\$, 68304604A\$,
68304605A\$, 68305320A\$, 68305321A\$, 68361668A\$, 68361669A\$,
68361672A\$, 68361673A\$, 68361680A\$, 68361681A\$

Part Description: SIDE STEP - TUBULAR CHROME RT

Issue For Dealer awareness, HD truck, eliminate 1 of 2 M8 Joints for Sidestep bracket to Body
Description: Attachment, Bolt and rivet (06102165AA, 06511062AA) per TCR # 402632, CN 80403-T18