



FCA CARIBBEAN WARRANTY BULLETIN

TO: Dealer Principal, Service Manager,
Service Advisor and Warranty Claims
Administrator

NO: ID-26-31

DATE: June 3, 2026

SUBJECT: Claim Submission for Hurricane
Spark Plug Repair (Rev. B)

FOR: Puerto Rico and US Virgin Islands

*****Revisions are noted in Red*****

PURPOSE:

This bulletin provides instructions for the proper claim submission of spark plug repairs using Labor Operations (LOPs):

- 081702E1: Spark Plugs; 2.0L Turbo Gas Engine (EVO) – One Cylinder or Multiple; Test, Clean, or Replace; and related LOP
- 08170253: Spark plugs; each additional spark Plug (one); Test, Clean or Replace.

Effective 5/28/2026, **spark plugs for the 2026 MY Jeep Grand Cherokee (WL) with a 2.0L Hurricane 4 Turbo Engine (Sales Code EC7) are no longer subject to STAR Center restriction.**

The part numbers are:

- 68540598AB for main chamber (qty. 4)
- 68506398AA for pre chamber (qty. 4)

The **2.0L Hurricane 4 Turbo Engine (Sales Code EC7)** remains on **STAR Center restriction** for all other diagnostic and repair conditions.

TIMING:

Effective with repairs opened on or after May 28, 2026

ACTION:


STAR Online number S2618000003 covers how to inspect and determine if the Spark Plugs or engine require replacement.

If the repair is determined to be Spark Plugs replacement (not the engine), **all eight (8) spark plugs (68540598AB for main chamber, 68506398AA for pre chamber) are to be replaced and photos of each spark plug, with the cylinder number and chamber (main or pre) identified, are required to be attached in the claim for approval.** Cylinder and chamber identification can be on the image or as the attachment name.

LOP 081702E1 should be submitted as the primary LOP. LOP 08170253 should be submitted six (6) times as related LOPs. Message Code RP1 will set on all claims. Please put the claim in "RA" for Warranty Contact Center review.




Photos are required showing the replaced (fouled) or damaged but intact spark plug(s). See the photo examples below.



**Porcelain Broken
But Still on Plug**



Figures 1 and 2 show all spark plugs from the engine organized so they can be easily identified once they are removed from the engine.



ADDITIONAL INFORMATION:

After the spark plug(s) are replaced, fill the vehicle with **premium** fuel using LOP 95140350. **Please attach a copy of the fuel receipt for approval.**

Please ensure all affected dealership personnel are aware of this bulletin.

WARRANTY OPERATIONS



CHRYSLER DODGE



FIAT

Jeep



©2026 FCA US LLC. All Rights Reserved. Chrysler, Dodge, Jeep, Ram, Mopar, SRT and HEMI are registered trademarks of FCA US LLC. ALFA ROMEO and FIAT are registered trademarks of FCA Group Marketing S.p.A., used with permission.

FCA International Operations LLC reserves the right to change any or all of the rules set forth in the Warranty Administration Manual by means of Warranty Bulletins and also by making the amended manual available to you on DealerCONNECT.