



SSM 54936 2025 Explorer - Platinum - Chirp Sound Instead Of Horn Honk When Locking Or Remote Starting Vehicle

Some 2025 Explorer Platinum vehicles may exhibit a chirp sound instead of a horn honk when locking or remote starting the vehicle. This is intended operation after a recent over-the-air (OTA) update that enabled the open on approach feature. No diagnostics or repairs should be performed for this condition.