

02-203: Mercury Warning Label Replacement

6/12/2026

 [Edit](#)  [Clone](#)

02-203

Subject

Mercury Warning Label Replacement

Whats New Abstract

Certain Kenworth chassis have updated Mercury Warning Labels available for installation.

Condition

An updated Mercury Warning Label is available for installation. To ensure state regulatory requirements are met, this update will equip the chassis with the most accurate information. **Labels are being mailed to customers and can be installed by customers.**

Chassis Affected

619 US vehicle model year 2026-2027 C500, T800, and W900 manufactured between 08/04/2025 and 03/16/2026 equipped with a non-compliant Mercury Warning Label

Parts

Labels will be shipped to customers. Dealers do not need to order labels.

Quantity	Part Number	Description
1	S53-1478-200	LABEL-MERCURY WARNING EN/SP

Attachments

- [02-203 Mercury Warning Label Replacement Chassis List](#)
- [02-203 Mercury Warning Label Replacement Customer Letter](#)



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

[Date]

Subject: 02-203 Mercury Warning Label Replacement

Expiration Date: None



FIELD SERVICE CAMPAIGN

This notice applies to your vehicle(s) with VIN(s) at the bottom or back of this page.

Dear Kenworth Customer,

Kenworth Truck Company has determined that certain C500, T800, and W900 vehicles manufactured between 08/04/2025 and 03/16/2026 require updated Mercury Warning Labels.

What is the problem?	A compliant Mercury Warning Label is required to meet state regulatory requirements.
What will your dealer do?	This compliant Mercury Warning Label is being provided to owners.
What should you do?	Follow the steps below to install the updated Mercury Warning label provided in this letter.

Label Replacement Instructions

1. Clean the area and install the new Mercury Warning Label on the upper-right driver-side door jamb.
2. Remove the existing Mercury Warning Label from the upper-left passenger-side door jamb.
3. Clean the area and remove any remaining adhesive.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com.

If you no longer own the vehicle(s), please send an email to servicebulletins@paccar.com with the complete VIN(s) and the name and address of the new owner.

We appreciate your attention to this matter and value your loyalty to Kenworth and its dealer network.

Sincerely,

Kenworth Customer Service