

GPOP - Issue Review System

Part Number: 68583994A\$, 68710847A\$, 68751672A\$, 68751673A\$, 68751690A\$,
68751691A\$

Part Description: POWER RUNNING BOARD MOTOR

Issue Description: Power Side-Steps/Running Boards not working properly, stuck or inoperable due to DTCs:
B1DB2-13 - Left Power Side Step Motor - Circuit Open / B1DB3-13 - Right Power Side Step
Motor - Circuit Open B1DB4-39 - Left Power Side Step Position Sensor - Signal Has Too
Few Pulses / B1DB5-39 - Right Power Side Step Position Sensor - Signal Has Too Few
Pulses Please do not replace the motors or the module if you're seeing this DTCs coming up
Write/record the DTCs in the narrative Please refer to the DTC service manuals available in
the Service Library to root cause and repair accordingly