

 Preview Solution CBR-2590-2

## Instrument Cluster Going Dark (Blackout) - AN (4) - PR - VN (4)

Published 16 June 2026

### Valid For

Mack Chassis - AN (4), PR

Volvo Chassis - VN (4)

Model Year - 2024 to current

The purpose of this CBR is to provide steps on how to correct a customer complaint of instrument cluster going dark (blackout) situation.

**Ensure the LATEST service pack is installed on the vehicle BEFORE utilizing the kit below.**

If you encounter an instrument cluster going dark or a black out situation, use accessory kit 26195497. This will apply software to the instrument cluster and correct any blackout complaint.

### Related links and attachments

No links or attachments available



#### Share

to others that might find it helpful



#### Feedback

[Give feedback](#)

to help improve the content of this article