

and that all claim filing requirements are met.

Use the following coding when submitting your warranty claim:

PPD Part Number	Part Description	Claim Type	Failure Location
2314736 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2314737 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2383578 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2383579 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2394547 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2394548 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2403200 (PEX)	FUEL INJECTOR	Engine	044-004-001
2403201 (PEX)	FUEL INJECTOR	Engine	044-004-001
2403775 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2403776 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2403777 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2403778 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2423651 (PEX)	FUEL INJECTOR	Engine	044-004-001
2423652 (PEX)	FUEL INJECTOR	Engine	044-004-001
2423653 (PEX)	FUEL INJECTOR	Engine	044-004-001
2423654 (PEX)	FUEL INJECTOR	Engine	044-004-001
2426853 (PEX)	INJECTOR, MX-11, EPA21/24	Engine	044-004-001
2426854 (PEX)	INJECTOR, MX-13, EPA21/24	Engine	044-004-001
2426855 (PEX)	INJECTOR, MX-11, EPA21/24	Engine	044-004-001
2426856 (PEX)	INJECTOR, MX-13, EPA21/24	Engine	044-004-001
2428773 (PEX)	FUEL INJECTOR	Engine	044-004-001
2428774 (PEX)	INJECTOR, MX-13, CARB 24	Engine	044-004-001
2429854 (PEX)	FUEL INJECTOR	Engine	044-004-001
2429855 (PEX)	FUEL INJECTOR	Engine	044-004-001

a defect in material and/or factory workmanship. Reimbursement will include:

- Parts
- Labor
- Consumables (when not reusable)

PROACTIVE REPAIRS ARE NOT COVERED BY THIS PROGRAM.

Towing will only be covered if 'engine' emission component failure occurs within the base engine period of 24 months/250,000 miles/6,250 hours, whichever comes first. Outside of base engine coverage, towing and travel are excluded.

PACCAR will pay for reasonable labor costs for engine removal and reinstallation when necessary to repair a warrantable failure.

2023 (MX-11)	<p>2314736 (PEX)⁽¹⁾</p> <p>2383578 (PEX)⁽¹⁾</p> <p>2394547 (PEX)⁽¹⁾</p> <p>2403775 (PEX)⁽¹⁾</p> <p>2403200 (PEX)⁽¹⁾</p> <p>2403777 (PEX)⁽¹⁾</p> <p>2423651 (PEX)⁽¹⁾</p> <p>2423653 (PEX)⁽¹⁾</p> <p>2426853 (PEX)⁽¹⁾</p> <p>2426855 (PEX)⁽¹⁾</p> <p>2429854 (PEX)⁽¹⁾</p> <p>2428773 (PEX)⁽¹⁾</p> <p>2452061 (PEX)⁽¹⁾</p> <p>2460409 (PEX)⁽¹⁾</p> <p>2460411 (PEX)⁽¹⁾</p> <p>2460413 (PEX)⁽¹⁾</p> <p>2434418 (PEX)⁽²⁾</p> <p>2461235 (PEX)⁽²⁾</p> <p>2477784 (PEX)⁽²⁾</p> <p>2477786 (PEX)⁽²⁾</p> <p>2477862 (PEX)⁽²⁾</p> <p>2477864 (PEX)⁽²⁾</p> <p>2491046 (PEX)⁽²⁾</p>	Fuel Injector
--------------	--	---------------

⁽¹⁾Part added in a previous update.

⁽²⁾Part added in latest update.

If there is a failure of any of the parts listed above, submit a warranty claim through PACCAR Registration

and Warranty System (PRWS). Ensure the correct VIN number and Causal Part removed from the vehicle are on the submitted claim.

Attachments

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines US Customer Letter](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines US Customer Letter – Spanish](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines CAN Customer Letter](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines CAN Customer Letter - French](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines Chassis List](#)



Kenworth Truck Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE033: MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Kenworth Customer,

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless you experience a problem with your vehicle.

This letter has been sent to inform you that Kenworth Truck Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty Coverage (EWC Code 9202164)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737 (PEX) ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
	2383579 (PEX) ⁽¹⁾	
	2394548 (PEX) ⁽¹⁾	
	2403776 (PEX) ⁽¹⁾	
	2403201 (PEX) ⁽¹⁾	
	2403778 (PEX) ⁽¹⁾	
	2423652 (PEX) ⁽¹⁾	
	2423654 (PEX) ⁽¹⁾	
	2426854 (PEX) ⁽¹⁾	
	2426856 (PEX) ⁽¹⁾	
	2429855 (PEX) ⁽¹⁾	
	2428774 (PEX) ⁽¹⁾	
	2452062 (PEX) ⁽¹⁾	
	2460410 (PEX) ⁽¹⁾	
	2460412 (PEX) ⁽¹⁾	
	2460414 (PEX) ⁽¹⁾	
2434417 (PEX) ⁽²⁾		
2461236 (PEX) ⁽²⁾		
2477785 (PEX) ⁽²⁾		
2477787 (PEX) ⁽²⁾		



A PACCAR COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

	2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾	
Fuel Injector (MX-11, EPA21)	2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
<p>⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.</p>		

If you have previously paid to replace one of the components listed in the tables above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Kenworth Dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When contacting your selected Kenworth dealer, refer to Extended Warranty Code (EWC) **9202164** and the VIN listed on this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.
Sincerely,



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

Kenworth Customer Service



Kenworth Truck Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE033: MX Component Specific Emissions Warranty for EMY2023
 PACCAR MX-11 and MX-13 Engines
 Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Kenworth Customer,

This notice is sent to you in accordance with the requirements of the Canadian Environmental Protection Act, 1999.

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless you experience a problem with your vehicle.

This letter has been sent to inform you that Kenworth Truck Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty Coverage (EWC Code 9202164)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737 (PEX) ⁽¹⁾	Inefficient fuel injector performance ⁽¹⁾ can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
	2383579 (PEX) ⁽¹⁾	
	2394548 (PEX) ⁽¹⁾	
	2403776 (PEX) ⁽¹⁾	
	2403201 (PEX) ⁽¹⁾	
	2403778 (PEX) ⁽¹⁾	
	2423652 (PEX) ⁽¹⁾	
	2423654 (PEX) ⁽¹⁾	
	2426854 (PEX) ⁽¹⁾	
	2426856 (PEX) ⁽¹⁾	
	2429855 (PEX) ⁽¹⁾	
	2428774 (PEX) ⁽¹⁾	
	2452062 (PEX) ⁽¹⁾	
	2460410 (PEX) ⁽¹⁾	
	2460412 (PEX) ⁽¹⁾	
	2460414 (PEX) ⁽¹⁾	
2434417 (PEX) ⁽²⁾		
2461236 (PEX) ⁽²⁾		



A PACCAR COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

	2477785 (PEX) ⁽²⁾ 2477787 (PEX) ⁽²⁾ 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾	
Fuel Injector (MX-11, EPA21)	2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
<p>⁽¹⁾ Components that were included in a previous letter.</p> <p>⁽²⁾ Additional component added to Extended Warranty Coverage.</p>		

If you have previously paid to replace one of the components listed in the tables above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Kenworth Dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest dealer please scan the QR code at the top of this letter or use the Dealer Locator at www.Kenworth.com. When contacting your selected Kenworth dealer, refer to Extended Warranty Code (EWC) **9202164** and the VIN listed on this letter.



A **PACCAR** COMPANY

Kenworth Truck Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Kenworth Customer Service

CE033 - MX Component-Specific Emissions Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines

6/19/2026

 [Edit](#)  [Clone](#)

CE033

MX Component-Specific Emissions Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines

Whats New Abstract

14 fuel injector part numbers (seven for MX-11 and seven for MX-13 engines) have been added to this warranty policy.

Introduction

U.S. & Canadian Federal emissions regulations require that the warranty coverage is a period of ten (10) years or 435,000 miles/700,000 km/22,000 engine hours, whichever comes first, from the original warranty registration date for these specific components on the MY2023 PACCAR MX-11 and MX-13 Engines. PACCAR has implemented the extension and it is effective retroactively unless the part is listed as ineligible for reimbursement below.

Revision

06/19/2026: 14 fuel injector part numbers (seven for MX-11 and seven for MX-13 engines) have been added to this warranty policy.

07/02/2025: 32 fuel injector part numbers (16 for MX-11 and 16 for MX-13) have been added to this warranty policy.

Condition

Units that have coverage under this warranty will be identified in Service Information Record (SIR):

Sales Code	Coverage Description
9485372	EW: MX Emissions 10yr/435K Miles (700K KM) – Engine MY2023

Submit a long-form warranty claim through PRWS, using the applicable claim type shown in the chart below, for any repair that meets the requirements of this bulletin. Please ensure the correct VIN number

is selected and that all claim filing requirements are met.

Use the following coding when submitting your warranty claim:

PPD Part Number	Part Description	Claim Type	Failure Location
2314736 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2314737 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2383578 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2383579 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2394547 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2394548 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2403200 (PEX)	FUEL INJECTOR	Engine	044-004-001
2403201 (PEX)	FUEL INJECTOR	Engine	044-004-001
2403775 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2403776 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2403777 (PEX)	INJECTOR, MX-11, EPA21	Engine	044-004-001
2403778 (PEX)	INJECTOR, MX-13, EPA21	Engine	044-004-001
2423651 (PEX)	FUEL INJECTOR	Engine	044-004-001
2423652 (PEX)	FUEL INJECTOR	Engine	044-004-001
2423653 (PEX)	FUEL INJECTOR	Engine	044-004-001
2423654 (PEX)	FUEL INJECTOR	Engine	044-004-001

2426853 (PEX)	INJECTOR, MX-11, EPA21/24	Engine	044-004-001
2426854 (PEX)	INJECTOR, MX-13, EPA21/24	Engine	044-004-001
2426855 (PEX)	INJECTOR, MX-11, EPA21/24	Engine	044-004-001
2426856(PEX)	INJECTOR, MX-13, EPA21/24	Engine	044-004-001
2428773 (PEX)	FUEL INJECTOR	Engine	044-004-001
2428774 (PEX)	INJECTOR, MX-13, CARB 24	Engine	044-004-001
2429854 (PEX)	FUEL INJECTOR	Engine	044-004-001
2429855 (PEX)	FUEL INJECTOR	Engine	044-004-001
2452061 (PEX)	FUEL INJECTOR	Engine	044-004-001
2452062 (PEX)	FUEL INJECTOR	Engine	044-004-001
2460409 (PEX)	FUEL INJECTOR	Engine	044-004-001
2460410 (PEX)	FUEL INJECTOR	Engine	044-004-001
2460411 (PEX)	FUEL INJECTOR	Engine	044-004-001
2460412 (PEX)	FUEL INJECTOR	Engine	044-004-001
2460413 (PEX)	FUEL INJECTOR	Engine	044-004-001
2460414 (PEX)	FUEL INJECTOR	Engine	044-004-001
2434417 (PEX)	FUEL INJECTOR	Engine	044-004-001
2434418 (PEX)	FUEL INJECTOR	Engine	044-004-001
2461235 (PEX)	FUEL INJECTOR	Engine	044-004-001
2461236 (PEX)	FUEL INJECTOR	Engine	044-004-001
2477784 (PEX)	FUEL INJECTOR	Engine	044-004-001

2477785 (PEX)	FUEL INJECTOR	Engine	044-004-001
2477786 (PEX)	FUEL INJECTOR	Engine	044-004-001
2477787 (PEX)	FUEL INJECTOR	Engine	044-004-001
2477862 (PEX)	FUEL INJECTOR	Engine	044-004-001
2477863 (PEX)	FUEL INJECTOR	Engine	044-004-001
2477864 (PEX)	FUEL INJECTOR	Engine	044-004-001
2477865 (PEX)	FUEL INJECTOR	Engine	044-004-001
2491046 (PEX)	FUEL INJECTOR	Engine	044-004-001
2491047 (PEX)	FUEL INJECTOR	Engine	044-004-001

For reimbursement of past repairs, unless noted above as not eligible, file a claim in accordance with the warranty procedure manual.

Attach an invoice and receipt to the claim to document the repair and payment made.

In addition, attach receipt of reimbursement made to customer for the initial invoice/costs of repair.

Retroactive claims without these items will be denied.

Warranty

The emissions warranty will cover the repair costs for any failure of an emissions-related part described in this bulletin that results under normal use and service, caused by a warrantable failure, which must be the result of a defect in material and/or factory workmanship. Reimbursement will include:

- Parts
- Labor
- Consumables (when not reusable)

i NOTE
Cummins-powered chassis do not have Extended Emissions Coverage under this bulletin.

PROACTIVE REPAIRS ARE NOT COVERED BY THIS PROGRAM.

Towing will only be covered if 'engine' emission component failure occurs within the base engine period of 24 months/250,000 miles/6,250 hours, whichever comes first. Outside of base engine coverage,

towing and travel are excluded.

PACCAR will pay for reasonable labor costs for engine removal and reinstallation when necessary to repair a warrantable failure.

The emissions warranty is retroactive and applies to qualifying warrantable failures that customers have

already had repaired at their expense.

These components qualify for coverage on EMY2023 PACCAR MX-11 and MX-13 engines:

Engine Model Year	PPD Part Number	Part Description
2023 (MX-13)	2314737 (PEX) (1)	Fuel Injector
	2383579 (PEX) (1)	
	2394548 (PEX) (1)	
	2403776 (PEX) (1)	
	2403201 (PEX) (1)	
	2403778 (PEX) (1)	
	2423652 (PEX) (1)	
	2423654 (PEX) (1)	
	2426854 (PEX) (1)	
	2426856 (PEX) (1)	
	2429855 (PEX) (1)	
	2428774 (PEX) (1)	
	2452062 (PEX) (1)	
	2460410 (PEX) (1)	
	2460412 (PEX) (1)	
	2460414 (PEX) (1)	
	2434417 (PEX) (2)	
	2461236 (PEX) (2)	
	2477785 (PEX) (2)	
	2477787 (PEX) (2)	
2477863 (PEX) (2)		
2477865 (PEX)		

	(2) 2491047 (PEX) (2)	
2023 (MX-11)	2314736 (PEX) (1) 2383578 (PEX) (1) 2394547 (PEX) (1) 2403775 (PEX) (1) 2403200 (PEX) (1) 2403777 (PEX) (1) 2423651 (PEX) (1) 2423653 (PEX) (1) 2426853 (PEX) (1) 2426855 (PEX) (1) 2429854 (PEX) (1) 2428773 (PEX) (1) 2452061 (PEX) (1) 2460409 (PEX) (1) 2460411 (PEX) (1) 2460413 (PEX) (1) 2434418 (PEX) (2) 2461235 (PEX) (2) 2477784 (PEX) (2) 2477786 (PEX) (2) 2477862 (PEX) (2) 2477864 (PEX) (2) 2491046 (PEX)	Fuel Injector

(2)

(1)Part added in a previous update.

(2)Part added in latest update.

If there is a failure of any of the parts listed above, submit a warranty claim through PACCAR Registration and Warranty System (PRWS). Ensure the correct VIN number and Causal Part removed from the vehicle are on the submitted claim.

Attachments

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines Chassis List](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines US Customer Letter](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines US Customer Letter – Spanish](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines CAN Customer Letter](#)

[CE033 MX Component Specific Emissions Extended Warranty for EMY2023 PACCAR MX-11 and MX-13 Engines CAN Customer Letter - French](#)



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE033: MX Component Specific Emissions Extended Warranty for
 EMY2023 PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Peterbilt Customer,

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless your vehicle experiences a problem.

This letter has been sent to inform you that Peterbilt Motors Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty (EWC Code 9485372)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737 (PEX) ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
	2383579 (PEX) ⁽¹⁾	
	2394548 (PEX) ⁽¹⁾	
	2403776 (PEX) ⁽¹⁾	
	2403201 (PEX) ⁽¹⁾	
	2403778 (PEX) ⁽¹⁾	
	2423652 (PEX) ⁽¹⁾	
	2423654 (PEX) ⁽¹⁾	
	2426854 (PEX) ⁽¹⁾	
	2426856 (PEX) ⁽¹⁾	
	2429855 (PEX) ⁽¹⁾	
	2428774 (PEX) ⁽¹⁾	
	2452062 (PEX) ⁽¹⁾	
	2460410 (PEX) ⁽¹⁾	
	2460412 (PEX) ⁽¹⁾	
2460414 (PEX) ⁽¹⁾		



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

	2434417 (PEX) ⁽²⁾ 2461236 (PEX) ⁽²⁾ 2477785 (PEX) ⁽²⁾ 2477787 (PEX) ⁽²⁾ 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾	
Fuel Injector (MX-11, EPA21)	2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.		

If you have previously paid to replace any of the components listed in the table above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Peterbilt



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When contacting your selected dealer, refer to Extended Warranty Code (EWC) **9485372** and the VIN listed below or on the back of this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Peterbilt Customer Service



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

[Date]

Subject: CE033: MX Component Specific Emissions Extended Warranty for
 EMY2023 PACCAR MX-11 and MX-13 Engines

Expiration Date: None



This notice applies to your vehicle; Your VIN(s) can be found on the front or back of this page.

Dear Peterbilt Customer,

This notice is sent to you in accordance with the requirements of the Canadian Environmental Protection Act, 1999.

This is not a recall or campaign. You do not need to schedule an appointment with your dealer unless your vehicle experiences a problem.

This letter has been sent to inform you that Peterbilt Motors Company has extended the warranty coverage on certain emissions components installed on your vehicle(s). Your vehicle(s) contain(s) one or more of the parts listed in this letter. **No action is needed on your part.**

The Emissions Warranty Coverage for the components listed in the table below has been extended to 10 years, 435,000 vehicle miles/700,000 km, or 22,000 engine hours from the original warranty registration date, whichever comes first.

Table 1 Parts Covered by Extended Warranty (EWC Code 9485372)

Part Name	Part Number	Result of Failure
Fuel Injector (MX-13, EPA21)	2314737 (PEX) ⁽¹⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
	2383579 (PEX) ⁽¹⁾	
	2394548 (PEX) ⁽¹⁾	
	2403776 (PEX) ⁽¹⁾	
	2403201 (PEX) ⁽¹⁾	
	2403778 (PEX) ⁽¹⁾	
	2423652 (PEX) ⁽¹⁾	
	2423654 (PEX) ⁽¹⁾	
	2426854 (PEX) ⁽¹⁾	
	2426856 (PEX) ⁽¹⁾	
	2429855 (PEX) ⁽¹⁾	
	2428774 (PEX) ⁽¹⁾	
	2452062 (PEX) ⁽¹⁾	
2460410 (PEX) ⁽¹⁾		



Peterbilt Motors Company
 Customer Service Department
 C/O PACCAR Parts
 750 Houser Way North
 Renton, WA 98057
 (425) 828-5888

	2460412 (PEX) ⁽¹⁾ 2460414 (PEX) ⁽¹⁾ 2434417 (PEX) ⁽²⁾ 2461236 (PEX) ⁽²⁾ 2477785 (PEX) ⁽²⁾ 2477787 (PEX) ⁽²⁾ 2477863 (PEX) ⁽²⁾ 2477865 (PEX) ⁽²⁾ 2491047 (PEX) ⁽²⁾	
Fuel Injector (MX-11, EPA21)	2314736 (PEX) ⁽¹⁾ 2383578 (PEX) ⁽¹⁾ 2394547 (PEX) ⁽¹⁾ 2403775 (PEX) ⁽¹⁾ 2403200 (PEX) ⁽¹⁾ 2403777 (PEX) ⁽¹⁾ 2423651 (PEX) ⁽¹⁾ 2423653 (PEX) ⁽¹⁾ 2426853 (PEX) ⁽¹⁾ 2426855 (PEX) ⁽¹⁾ 2429854 (PEX) ⁽¹⁾ 2428773 (PEX) ⁽¹⁾ 2452061 (PEX) ⁽¹⁾ 2460409 (PEX) ⁽¹⁾ 2460411 (PEX) ⁽¹⁾ 2460413 (PEX) ⁽¹⁾ 2434418 (PEX) ⁽²⁾ 2461235 (PEX) ⁽²⁾ 2477784 (PEX) ⁽²⁾ 2477786 (PEX) ⁽²⁾ 2477862 (PEX) ⁽²⁾ 2477864 (PEX) ⁽²⁾ 2491046 (PEX) ⁽²⁾	Inefficient fuel injector performance can lead to insufficient regeneration and high soot loading of DPF due to uneven fuel burning.
⁽¹⁾ Components that were included in a previous letter. ⁽²⁾ Additional component added to Extended Warranty Coverage.		



Peterbilt Motors Company
Customer Service Department
C/O PACCAR Parts
750 Houser Way North
Renton, WA 98057
(425) 828-5888

If you have previously paid to replace any of the components listed in the table above, you may be eligible for reimbursement of the cost of parts and labor. Please provide your Peterbilt dealer with a receipt for the repair and your dealer will file a claim on your behalf. If approved, your dealer will issue reimbursement.

To locate your nearest Peterbilt dealer, please scan the QR code at the top of this letter or use Find a Dealer at www.Peterbilt.com. When contacting your selected dealer, refer to Extended Warranty Code (EWC) **9485372** and the VIN listed below or on the back of this letter.

If you are the lessor of this vehicle, federal regulations require you to forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, please email the last 8 digits of the VIN and the new owner's name and address to servicebulletins@paccar.com.

Sincerely,

Peterbilt Customer Service