



STAR ONLINE PUBLICATION



Case Number: S2623000045

Release Date: June 2026

Models Affected: 2026 Jeep Recon – (EJ)

Symptom/Vehicle Issue: Power Top Units Showing Stored DTC. Even When Cleared DTC Will Show Back Up as Stored after Sleep Cycle.

Discussion/Diagnosis: If WiTech shows stored DTC's U0020-00-(Can B BUS Off Performance), B2206-87-(Current VIN Missing), and/or B2582-23-(Roof Open Close Switch-Signal Stuck Low), please proceed with clearing DTC's and DO NOT replace any parts if power top is functioning correctly. When flashing the PTCM and the p/n does not update, Do not perform any repairs if the power top is functioning correctly.

Repair Procedure: No further repairs are advised currently. This concern is currently under investigation with engineering. A future update will be released when available.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.