

ShoreLand'r®

SERVICE BULLETIN

SUBJECT: Inspection and Replacement of Trailer Jack 1500 lb.	No: 1107
	DATE: 6/5/2026
	PRODUCT OR PARTS: Trailers manufactured with a 1500lb trailer jack (3310104) Between 04/01/26-06/01/26

PURPOSE

Owners and dealers of trailers equipped with Trailer Jack P/N 3310104 (1,500 lb. capacity).

Certain trailer jacks may experience operational issues, including binding or seizing during normal use. In some cases, the handle-to-gear retaining pin may slip out of its seated slot, resulting in improper jack operation.

Affected trailers may be located throughout the field at dealer inventory or in customer ownership.

EFFECTED PRODUCTS

Trailer Jack, 1,500 lb. Capacity
Trailers manufactured from 04/01/2026 through 06/01/2026

Important: Trailers with the color inspection dot on the jack near the handle have already been inspected and verified. These trailers are not included in this bulletin and require no further action. Dots may be green or pink.

WARRANTY INFORMATION

If a trailer falls within the affected production range and is experiencing the conditions described in this bulletin, please contact Midwest customer service representative Roxanne Alexander at ralexander@midwestindustries.com. Provide the following information when requesting a replacement jack:

- Trailer VIN
- Clear photo of the installed jack
- Shipping information

Upon verification, a replacement jack will be shipped. A return UPS call tag may be provided via email for the return of the jack.

Replacement of qualifying jacks under this bulletin will be handled at no charge to the dealer/customer. Labor for the replacement of the jack will be paid to dealers in the amount of \$50 per jack. No warranty claim will need to be submitted for this bulletin.



ADDITIONAL INFORMATION TO FOLLOW



Inspection dot- no replacement needed

Manf Date located on the back right corner of the frame

