

# TECHNICAL UPDATE – TIGER SPORT 660 & TIGER SPORT 800 SCREEN MOUNT ARMS

This notice outlines a potential fitment issue with the screen adjustment arm on all model year Tiger Sport 660 and Tiger Sport 800 models and provides updated installation guidance.

**Models affected:** Tiger Sport 660 (all model years), Tiger Sport 800 (all model years)

**VIN range:** All.

## **What is the nature of concern?**

The mounting arm may become damaged during fitment.

## **How will this concern be found?**

The mechanism may immediately become loose or become loose soon after.

## **What is the impact to the customer?**

The screen may not retain its position.

## **What is Triumph doing?**

Triumph has carried out an investigation into this concern and has found that the method of initial fitment of the assembled screen adjustment arm is the cause.

## **What do I need to do?**

Dealers are requested to ensure that they apply continuous outwards pressure in the areas indicated below while the mount arms, or complete assembly, are rotated into the final position.



## **Warranty claim information:**

Warranty claims submitted after this update will be rejected.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.