

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A6, S6 Sportback e-tron, Q6 e-tron, Q6 Sportback e-tron, SQ6 e-tron, and SQ6 Sportback e-tron	2025	All	0003 – Brake electronics Software version: 0379

Customer states:

The warning message “Parking brake: fault. Please contact workshop” appears.

Workshop findings:

The DTC “**C1100F0** Hydraulic assistance not possible” is logged with symptom 4593156 in address 0003.

Technical Background

Hydraulic support to activate the parking brake cannot be performed due to a component protection function.

Production Solution

Since January 2026 with model year 2026.

Service

Please postpone the repair to mechanical components as there is currently no effective repair for the complaint described by the customer.

If DTC C1100F0 is logged in isolation, it can be remedied by releasing and reapplying the parking brake with a gear selected. This will cause the system to perform a check and remedy the issue itself.

If the DTC is logged in combination with other DTCs, the other DTCs must be worked through first as a priority. The DTC relating to hydraulic assistance is merely a result of these DTCs.

A combined software update is currently being implemented. It will be rolled out in stages for the different models and markets. All information about the current schedule and availability of the measure can be found in the central service info TSB 2081477, *00 Service info: central overview of combined software update 03.11.00/C PPE PPC - KD2 (refer to table for combined software update 03.20.00/C KD3).**

As a part of the process create a PSS record in the PSS database via the Pending Service Solutions (PSS) link found in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

Warranty

Replacing parts or attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Additional Information

All part and service references provided in this TSB (**2082278**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America LLC / Audi Canda, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.