



Connection offline

Technical Service Bulletin

Transaction No.: **2082160/1**

87 Service info: air flow intensity does not change when blower speed is greater than 4

Release date: Jun 1, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A3, S3, and RS3	2024 – 2025	All	All

The intensity of the air flow when using manual air conditioning does not change noticeably when the blower speed is greater than 4.

Technical Background

This is normal.

Production Solution

Not applicable.

Service

This TSB replaces Pending Service Solution (PSS) TSB 2079419, *87 PSS: Air flow intensity does not change when blower level is higher than 4.*

Not applicable.

Warranty

Replacing parts or attempting repairs will not fix the problem. Unjustified work/replacement parts will be charged back. Invoicing under warranty is not permitted.

Additional Information

All part and service references provided in this TSB (**2082160**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.