



Service Bulletin

Bulletin No.: PIT5544J

Date: June, 2026

PRELIMINARY INFORMATION

Subject: Normal Characteristic - Hydraulic Rush Noise from Power Steering Gear

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 2500HD	2016-2026		All	All	All	All
Chevrolet	Silverado 3500HD	2016-2026		All	All	All	All
GMC	Sierra 2500HD	2016-2026		All	All	All	All
GMC	Sierra 3500HD	2016-2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	NV8
Condition	Some customers may comment on a hydraulic rush or flow type noise from the power steering gear. The noise is most noticeable in the cab at idle, in park, with all accessories turned off.

Correction

NONE

This noise is a characteristic of the new Active Hydraulic Assist System RPO NV8 and no repairs should be made.

Version	10
Modified	01/18/2017 - Created on 10/13/2017 - Updated Model Years 10/12/2018 - Updated Model Years 10/14/2019 - Updated Model Years 03/05/2021 - Updated Model Years 09/01/2021 - Updated Model Years 12/14/2022 - Updated Model Years 05/22/2023 - Updated Model Years 01/24/2025 - Updated Model Years 6/23/2026 - Updated Model Years

