



Service Bulletin

Bulletin No.: PIC6654

Date: June, 2026

PRELIMINARY INFORMATION

Subject: Blank Head Up Display (HUD) Screen

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2027		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	RPO UV6 - Head Up Display
Condition	Some customers may notice a blank Head-Up Display (HUD) on the windshield that does not recover. He or she may comment that it is simply inoperative or appears to be broken.
Cause	Engineering is currently investigating an anomaly in the radio system that affects how the previously selected HUD brightness level is stored and retained across ignition cycles.

Correction

Using the HUD control panel in the outboard auxiliary display screen, located to the left of the main IPC screen, swipe left to access the HUD controls, then tap the brightness "up" button until the HUD image reappears.



7162922

Do not replace the HUD or Radio (Vehicle Control Unit) for this condition, as it will not permanently solve the problem. Engineering is investigating the concern. In the meantime, please advise the customer that they may continue to drive the vehicle. The PI will be updated or replaced with a TSB once a determination has been made.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0540709	Heads-Up-Display (HUD) – Customer Concern Not Duplicated (CCND)	0.3 hours

Version	1
Modified	06/29/26 Created on

