

Published
ID: 113070

Message

Target

Options

Over / Deny

Clone

Request

Communication

Publish Dates

- The Start Date is when the communication will be visible to dealers in DCMail.
- The End Date is when the communication will no longer be visible to dealers in DCMail.
- NOTE: End Dates are limited to one (1) year from the Start Date. If you wish to lengthen the End Date, you may extend it at any time after publish.

Start Date 6/29/2026 7:00 AM

End Date 7/20/2026 11:55 PM

Note: All times are EST

Extend End D

Title

What will display in DCMail for dealers to click on.
TIP: Keep titles short, but specific and eye catching.

SWITCH - HEADLAMP : INTERRUPTEUR - PHARE : INTERRUPTOR - FARO DELANTERO

Flagged for Reporting Agency

NO

Communication Summary

To increase search capability and visibility of your communication, please provide a brief summary or your message (140 characters max). This will display when dealers hover over your communication.

SWITCH - HEADLAMP : INTERRUPTEUR - PHARE : INTERRUPTOR - FARO DELANTERO

Message

The body of your communication. Use the formatting toolbar above to format text, insert tables, pictures, and/or hyperlinks.

Click Edit > Attach File to attach documents

IMPORTANT NOTES:

- Pictures must have unique file names. If you receive an error message when uploading a picture, it means the file name has already been chosen. Simply change your file name and try again.
- Communications cannot exceed more than 12MB; this includes images and text, and all attachments.

You have been identified as either having stock on hand or in transit to your dealership.

Please check and return suspect stock of part numbers: 68156061AD, 68156064AC, 68156065AC, 68156066AC, 68401933AB, 68575999AA, 68401934AB, 68668430AA, 68669032AA, 68669033AA, 68469535AA and 68576206AA. Please refer to QIR attachment.

Please return all parts back to your facing depot using Return Code 02, before 20th July 2026.

For replacement place new orders.

Return any open orders in process too. Direct questions regarding returns via email to mopardmail@stellantis.com.



Quality Inspection Request SWITCH – HEADLAMP Suspect Part Identification

29-June-2026

Part numbers: 68156061AD, 68156064AC, 68156065AC, 68156066AC, 68401933AB, 68575999AA, 68401934AB, 68668430AA, 68669032AA, 68669033AA, 68469535AA and 68576206AA.

Julian date code location:

Julian date code shown

0376: DDDY

37th Day of 2026

6th February 2026

Part in picture shown is suspect.

Part in picture below is suspect



Suspect parts: Parts built before Julian date code 1036 (13th April 2026) are suspect parts.



Demande d'inspection de la qualité

29-Juin-2026

INTERRUPTEUR – PHARE

Identification de la pièce suspecte

Les Numéro de pièces: 68156061AD,
68156064AC, 68156065AC, 68156066AC,
68401933AB, 68575999AA, 68401934AB,
68668430AA, 68669032AA, 68669033AA,
68469535AA et 68576206AA.

Emplacement du code de date Julien:

Code de date Julien affiché

0376 : JJJA

37e Jour de 2026

6 février 2026

La partie de l'image montrée est suspecte.

La partie de l'image ci-dessous est **suspecte**



Pièces suspectes: Les pièces construites avant le code de date julien **1036 (13 avril 2026)** sont des pièces suspectes.



Solicitud de Inspección de Calidad

29 de junio de 2026

INTERRUPTOR – FARO DELANTERO

Identificación de la parte sospechosa

Número de partes: 68156061AD, 68156064AC, 68156065AC, 68156066AC, 68401933AB, 68575999AA, 68401934AB, 68668430AA, 68669032AA, 68669033AA, 68469535AA y 68576206AA.

Ubicación del código de fecha juliana:

Se muestra el código de fecha juliano

0376 : DDDA

Día 37 de 2026

6 de febrero de 2026

Parte de la imagen del paquete que se muestra es sospechosa.

Parte en el paquete se muestra a continuación es **sospechoso**



Piezas sospechosas: Las piezas fabricadas antes del código de fecha juliana **1036** (**13 de abril de 2026**) son piezas sospechosas.