

2026 Plateau

L1: CUSTOMER STATES SOLAR SYSTEM QUIT WORKING, PLEASE INSPECT AND ADVISE FOR P-WAY WARRANTY. NOTE: GO POWER SENT A NEW ROOF PORT AND NEW SET OF WIRES IF NEEDED, PLEASE INSPECT AND ADVISE ON WHY THE MONITOR SHOWS NO SOLAR INPUT. INSPECT AND FOUND SOLAR INPUT PORT CABLES CAME APART.REMOVED AND REPLACED WITH NEW PORT AND CABLES THAT WERE SENT HERE @ NO CHARGE FOR CUSTOMER BY GO POWER RE SEALED AND TEST OPERATION, FOUND SOLAR IS NOW REGISTERING ON TOUCH PANEL. WORKING PER DESIGN. DONE. LABOR: 1.0 **1.0 approved.**