



Service Bulletin

Bulletin No.: PIT6006D

Date: July, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: Unable To Learn Additional Key Transmitters/ Back Up Antenna Location for Police Vehicles

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 New (RPO J22, VIN Digit 5 = A or D)	2022		All	All	All	All
Chevrolet	Silverado 1500	2023 - 2026		All	All	All	All
Chevrolet	Tahoe	2021 - 2026		All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	5W4 or 9C1 with RPO: BTM
Condition	Some technicians may state that they are unable to add additional key transmitters to the vehicles when equipped with the police package.
Cause	Unable to locate the fob pocket or backup antenna also known as the IMMO coil. Most police vehicles will not be equipped with a center seat or center console assembly, which is where the fob pocket/backup antenna is typically located. The following will show the location for the fob pocket/backup antenna that is used for learning new transmitters.

Correction

The following will show the location for the backup antenna/ Immo coil for learning new transmitters. Most police vehicle will not be equipped with a center seat or center console assembly.

For 2021-2025 Police Tahoe Models

The location for the fob pocket/backup antenna is located on the ledge right above the start/stop switch, as shown below. This is where the transmitter should be placed when learning new transmitters.



6312518

For 2022-2025 Silverado Police Models:

For vehicles equipped with RPO: 5Y1 then the pocket is shown below:


The location of the fob pocket/back up antenna is right above the SDM (restraint control module). Lift the flooring between the front seats to locate an indentation where the transmitter should be placed when learning new transmitters, as shown below.



6319206

Note: If the police vehicle has been upfitted, there may be a aftermarket center console or other items covering up this location.

For vehicles not equipped without RPO: 5Y1: The pocket is the standard center seat program location shown below:



6570370

Version	5
Modified	04/28/2023 - Created on. 02/19/2023- Updated models to add the 2024 model year. 03/11/2024- Update Silverado section to give the 2 locations of backup pocket. 08/04/2025=Update to add the 2025 model year 07/09/2026--Update to add the 2026 model year