

Date: 07/01/2026
CAL FTL 54-042

Subject: Removal of Driver Assistance Virtual Switches in Driver Display

Make: Freightliner

Model: Fifth Generation CASCADIA

Model Year Affected: 2027

Build Date Range: Selected Vehicles Built From Jan 12th, 2026 through June 25th, 2026.

Our records indicate that you are the owner of certain vehicles, and therefore DTNA has decided to share the following documentation with you.

Please see the attached communication in this email. We hope you find this information helpful.

Date: 07/01/2026
CAL FTL 54-042

Subject: Removal of Driver Assistance Virtual Switches in Driver Display

Make: Freightliner

Model: Fifth Generation CASCADIA

Model Year Affected: 2027

Build Date Range: Selected Vehicles Built From Jan 12th, 2026 through June 25th, 2026.

General Information:

DTNA will be updating vehicle parameters through an over-the-air update (POTA). These parameters will disable the driver display's virtual switches that allow the driver to toggle assistance features such as Side Guard Assist (SGA), Active Side Guard Assist (ASGA), Traffic Sign Display (TSD), and Active Speed Intervention (ASI).

Our records indicate that these virtual switches were intended to be disabled through sales code 72J-004. However, a programming error left these switches enabled, resulting in drivers having the unintended ability to disable these features.

A list of affected vehicle identification numbers (VINs) is shown in the attached sheet.

The following parameter adjustments will be performed remotely:

ECU	Domain Name	Parameter Name	From Part Number	From Value	To Part Number	To Value
ICUC01T	PID 0x45 (FTL config)	paramBSMMenu	A0444471221-001	[1] available	A0444471121-001	[0] not available
ICUC01T	PID 0x4001 (Vehicle config)	paramBSMTrailerConfig	A0434472821-001	[1] enabled	A0434472921-001	[0] disabled
ICUC01T	PID 0x45 (FTL config)	paramTSRMenu	A0444471621-001	[1] available	A0444471521-001	[0] not available
ECU	Domain Name	Parameter Name	From Part Number	From Value	To Part Number	To Value
ICC501T	PID 0x28 Virtual switch parameters	PT_BSM_SideGuardSw_AVL	A0574472021-001	[1] available	A0574471921-001	[0] not available
ICC501T	PID 0x43 FTL configuration	PD_MenuAvailability_TSR	A0714474921-001	[1] available	A0714474821-001	[0] not available

Follow the link below for POTA list;

<https://dtnacontent-dtna.prd.freightliner.com/content/dam/dtna-portal/en/service/cals/ftl/POTA%20list%20for%20CAL.xlsx>