

GPOP - Issue Review System

Part Number: 82219133A\$

Part Description: Trailer Tow Wiring Harness

Issue If after installing Trailer Tow Kit the DTCM will not PROXI / B2204-00 ECU
Description: CONFIGURATION MISMATCH sets active in the BCM / ODOMETER begins to blink, please open a STAR Case and await instruction.