



STAR ONLINE PUBLICATION



Case Number: S2623000048

Release Date: August 2026

Models Affected:

2024 – 2025 Jeep Wrangler (JL)

2024 – 2025 Jeep Gladiator (JT)

Symptom/Vehicle Issue:

Customer States Driver Seat Inoperative.

Discussion/Diagnosis:

Confirm the driver's seat has no power or limited motion. Perform a functional check of all seat motor operations. Check that the seat fuse F59 30A is not blown and verify proper fuse rating. Locate the seat harness under the seat cushion, paying close attention to the section routed near the Lumbar Switch. Inspect the harness for the following as has been noted in prior cases for the listed model years: Rubbing, chafing, pinched sections, Exposed copper or insulation damage. Check for signs of short-to-ground or short-to-power. See Fig 1 and Fig 2 below for the known areas of concern.

If damage is found, verify continuity of all affected circuits using the DVOM, and confirm that voltage and ground at the supply circuits are present at the seat motor connectors.

Repair Procedure:

Follow standard wiring harness repair procedures outlined in Service Library.

Replace or repair the rubbed section using OEM-approved splice and insulation methods.

Secure the harness away from seat frame edges, springs, or moving components using approved retainers and tape. Please verify that no further interference occurs during full-seat travel.

Reinstall seat components and perform a full functional test of all seat motors.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.



STAR ONLINE PUBLICATION



Fig #1



Fig #2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.