

Bulletin #: C32-0826-0643		☐ Take Note ☒ Take Action		 The Ultimate Driving Machine®
☐ Retail Operator	☐ Sales Pre-Owned	☐ Business Manager	☒ Parts & Accessories	
☐ General Manager	☐ Sales New Car	☐ Service	☐ Administration	
Name:		Phone Number:		
Title:		Source: Parts Logistics		
Date: August 21, 2026		Supersedes:		

BMW PARTS BULLETIN

TEC876 FASTENING ELEMENTS RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

17 11 8 482 944

Affected available inventory must not be used or sold.

Concerned are all parts shipped and delivered containing broken or missing tabs. Parts with all 4 tabs fully present are ok for use.

Your attention and information update is required on SRD Next>Parts Campaign by 08/27/2026.


Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC876 must appear in the text of your TEC claim. If you cannot locate the delivery number, please submit an IDS ticket to Parts Logistics>Returns>Claims>Quality>Claims for assistance.

TEC876 is valid from August 21, 2026, through September 04, 2026. The deadline for filing a claim under TEC876 is September 04, 2026. All parts must be returned to your facing RDC no later than September 18, 2026.

Please reorder the same part number as needed.

Affected Parts (NOT OK)

One or More Locking Tabs Not Fully Present



Non Affected Parts (OK)

All 4 Locking Tabs Are Fully Present

