

ATTENTION: Dealer Principal, Warranty Manager, Service Manager, Parts Manager
Freightliner Dealers – U.S. and Canada
Western Star and Sterling Dealers – U.S. and Canada
FCCC Dealers – U.S. and Canada
Thomas Built Buses Dealers – U.S. and Canada
Direct Warranty Customers – U.S. and Canada

Daimler Truck North America LLC

WARRANTY CAMPAIGNS DEPARTMENT

P.O. Box 4090

800-547-0712

Portland, Oregon 97208-4090

If you have questions about this Letter, please submit your inquiry using the **PNA App on the DTNA Portal**

REF #: ICI26-014

Effective: 08/25/2026

Release: 08/25/2026

SUBJECT: SF732 Revised Bulletin

This letter is to inform you that a revised bulletin for Field Service Campaign SF732 (Power Acumen Fuse) is now available on the DTNA Portal.

REVISION: The work instructions have been revised to include an additional note clarifying that the approved repair utilizes the 5 amp fuse specified in this bulletin.

If you have questions or need further information, contact the Warranty Campaigns Department by submitting an inquiry through the Prism Network Assistant (PNA) located on the DTNA Portal.

The information contained in this letter supersedes and supplements any related policies and procedures in any previously released bulletins, the Warranty Manual, and/or previously released letters. Failure to read or distribute this letter will not exempt addressees from compliance with the information contained herein.