



# Service Bulletin

Bulletin No.: PIT6517E

Date: August, 2026

## PRELIMINARY INFORMATION

**Subject: B174 Front View Camera Module (FCM) DTC U3000 Part Restriction Has Ended**

| Brand:    | Model:   | Model Year: |    | VIN: |     | Engine: | Transmission: |
|-----------|----------|-------------|----|------|-----|---------|---------------|
|           |          | from        | to | from | to  |         |               |
| Chevrolet | Colorado | 2024–2026   |    | All  | All | All     | All           |
| Chevrolet | Corvette | 2024–2025   |    | All  | All | All     | All           |
| GMC       | Canyon   | 2024–2026   |    | All  | All | All     | All           |

|                                   |                                                                                                                                                                                                                   |
|-----------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Involved Region or Country</b> | North America                                                                                                                                                                                                     |
| <b>Condition</b>                  | Some customers may comment on having the Service Engine Soon (SES) and/or Malfunction Indicator Lamp (MIL) illuminated.<br>When checking for DTCs the B174W Front View Camera (FCM) will have a U3000 as history. |
| <b>Cause</b>                      | Software anomaly in the B174W Front View Camera Module.                                                                                                                                                           |

### Correction

General Motors Product Quality Center (PQC) part restriction on B174 Front View Camera Module (FCM) has ended.

We would like to thank all dealers who participated in this restriction for their cooperation.

This B174 Front View Camera Module (FCM) can now be ordered through the regular GM CCA parts process or PQC process for required dealers (Canada).

|                 |                                                                                                                                                                                                                                 |
|-----------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Version</b>  | 5                                                                                                                                                                                                                               |
| <b>Modified</b> | 05/28/2026 - Created on<br>06/05/2026 - Updated title/subject line.<br>07/14/2026 - Updated Q5<br>07/30/2026 - Updated models and years<br>08/18/2026 - Updated models and years<br>08/24/2026 - Updated to end the restriction |

