

ATTENTION: Mercedes-Benz Dealer Principals, General Managers, Sales Managers, Service Managers & Parts Managers

Service Campaign Notification

July 10, 2026

Campaign #	Description	Replace the Transmission Control Unit
2026060005	26P2790503	

Campaign Details			
Total Population	68	Model(s)/ Platform(s)	S-Class (223)
Model Year(s)	2026		
Issue	The transmission control unit (VGS) in the automatic transmission does not comply with our currently valid specifications in the vehicles of the above-mentioned model series delivered to you. It is possible that the polarities of the magnets in the transmission control unit (VGS) have been swapped. This could in turn result in shift quality issues and gear lockouts.		
Remedy	MBUSA will conduct a service campaign. We therefore request that you replace the electrohydraulic controller unit (EHS) of the automatic transmission in the affected vehicles. Please refer to the attached work description for details on the operations required.		
Launch Date	Affected VINs will be flagged in VMI as “OPEN” on Friday, July 10, 2026.		
Warranty Claim Notice	Please note the campaign will close after the warranty claim has been submitted. This change can take at least one day to reflect in Netstar VMI.		

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Care Center at 1-800-FOR-MERCEDES.

