

Glass Roof: Observe Special Procedure for Removal and Installation, as well as Replacement Requirements (67/26)

Model Line: **Taycan (Y1A)**

Model Year: **2020 to 2026**

Equipment: **Glass roof (M-no. 3FG)**
Glass roof with electric tinting (**M-no. 3FP**)

Concerns: **Roof assembly**

Information: **In the current model year 2026, the existing fastening of the roof module on Taycan vehicles was changed from screw connection and bonding to just bonding.**
In light of this, the mounting of the roof module must be checked before removal and the same fastening method must be used again for installation.

Action: In the event of removal and installation, as well as of replacement of the roof module, attention must be paid to the following:

Installed roof module is bonded and additionally screwed (vehicles from model year 2020 to approx. November 2025)

- Re-bond **and** screw on roof assembly.

Work procedure see: **600655A4 Replacing roof assembly**



Information

It is **not** permitted to omit the screw connection on vehicles that previously had a screwed roof module.

Installed roof module is exclusively bonded (vehicles from approx. November 2025 to today)

- Re-bond roof assembly, do **not** use additional screws.

Work procedure see: **600655A4 Replacing roof assembly**

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.